



Pushing Performance



People | Power | Partnership

HARTING BLE Gateway Release Notes 2.1.0

1. Edition 2018

© HARTING IT Software Development, Espelkamp

All rights reserved, including those of the translation.

No part of this manual may be reproduced in any form (print, photocopy, microfilm or any other process), processed, duplicated or distributed by means of electronic systems without the written permission of HARTING IT Software Development GmbH & Co. KG, Espelkamp

Subject to alterations without notice.



History of Revisions

Version 2.1.0 (2018-10-08).....4

Version 2.1.0 (2018-11-07)

General

The BLE Gateway container version 2.1.0 ...

- requires MICA Base Firmware 4 or higher
- was tested and developed for RuuviTag Beacon, BOSCH CISS-DataStreamer, blukii Smart Beacon, TI CC2650STK
- requires activation of BLE in the Network settings on mobile MICA

New Features

Bug Fixes

Known Issues

- BLE discovery causes WLAN instabilities, if Advanced Roaming setting is set
- Connection based BLE devices (Bosch CISS, TI) can cause WLAN instabilities in some combination