



Pushing Performance



People | Power | Partnership

## HARTING CISS Gateway Release Notes 2.1.0

---

2. Edition 2018

© HARTING IT Software Development, Espelkamp

All rights reserved, including those of the translation.

No part of this manual may be reproduced in any form (print, photocopy, microfilm or any other process), processed, duplicated or distributed by means of electronic systems without the written permission of HARTING IT Software Development GmbH & Co. KG, Espelkamp

Subject to alterations without notice.



## History of Revisions

Version 2.0.0 (2018-08-10).....	4
Version 1.1.0 (2018-04-20).....	6

## **Version 2.1.0 (2018-10-08)**

### **General**

The CISS Gateway container version 2.1.0 ...

- requires MICA Base Firmware 2 or higher
- while MICA Base Firmware 4 is recommended
- was tested and developed for Bosch CISS with firmware 02.03.00

### **New Features**

- Providing a default MQTT subscriber
- Supporting container alias to address local containers by their name only (e.g. "MQTT" instead of "MQTT-mica-xyz.local")

### **Bug Fixes**

- Improve IPv6 name resolution

### **Known Issues**

- Detecting and reconnecting a CISS devices takes up to 60 seconds



## Version 2.0.0 (2018-08-10)

### General

The CISS Gateway container version 2.0.0 ...

- requires MICA Base Firmware 2 or higher
- was tested and developed for Bosch CISS with firmware 02.03.00

### New Features

- Providing firmware version information of connected Bosch CISS devices
- Providing firmware update function for Bosch CISS devices
- Supporting new subscriber types JDBC (for H2 databases) and Azure

### Bug Fixes

- Improve sensor initialization
- Improve sensor detection

### Known Issues

- Detecting and reconnecting a CISS devices takes up to 60 seconds
- To update a subscriber a click outside the input fields is needed before clicking "Apply"



## **Version 1.1.0 (2018-04-20)**

### **General**

- Initial Release

### **New Features**

-

### **Bug Fixes**

-

### **Known Issues**

-